

10 Attached documents

10.1 Wiring diagrams




Figure10-1 Wiring diagram

### 10.1.1 List of components

Table 14: List of components		
Acronym	Description	Type
TC1	Single phase transformer	0.230,400-0.24VAC / 8VA
FU1	Fuse 5 x 20	F100mA / 250V
FU2	Fuse 5 x 20	F500mA / 250V
INT1	Switch	TECNOMATIC HD1201F111
SQ1	Microswitch	PIZZATO FR501
KM1	Contactore	ABB B6-30-10-P